

## Separator Saves Parishioners

A worship center in Amarillo, Texas was having trouble keeping their cooling towers running at its designed efficiency. The maintenance team was spending 2 days during their quarterly PMs just on the tower basins. They contacted their local Puroflux representative to discuss options to a cleaner and more efficient cooling tower system. Puroflux and the local representative worked together to provide the worship center with a properly sized hydrocyclone separator along with a basin sweeper piping kit. The hydrocyclone separator along with basin sweeper piping has helped reduce the unscheduled maintenance and cut their quarterly PM time down to a single 8 hour day.



If you need assistance with your selection please contact your local Puroflux representative and be on your way to a cleaner and more efficient system.

2121 UNION PLACE • SIMI VALLEY, CA 93065  
PHONE: (805) 579-0216 • FAX: (805) 579-6005  
WWW.PUROFLUX.COM • SALES@PUROFLUX.COM